

Remondant  
#19

US EPA RECORDS CENTER REGION 5



466043

Brian Boyd PRINTED

NOT HIS PRINTING

BRIAN BOYD

# Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using ballpoint pen - INKLESS HARD

## HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 11125

1 PART A.

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous waste, solid, n.o.s.	ORM-E	NA9189				X	3000	X				1 Roll	T	K087
2. (Tar Decanter Sludge)	(12)													
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nugs</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 3 8 82	EXPECTED ARRIVAL DATE MONTH DAY YEAR 3 8 82
Transporter HWT ID No. 129 EN 29012	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kouch</i>	DATE RECEIVED MONTH DAY YEAR 3/8/82	

YEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kouch</i>	DATE DELIVERED MONTH DAY YEAR 3/8/82
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1. <i>D-01</i> 2. 3. 4.
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYD</i>	DATE RECEIVED MONTH DAY YEAR 3-8-82



IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE

CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;

7302 - 11125

# Jones & Laughlin Steel Corporation / an LTV company

## HAZARDOUS WASTE MANIFEST

Please TYPE or PRINT clearly, using  
a ballpoint pen - **LESS HARD**

DOCUMENT NO. **7302** - **02072**

**1 PART A**

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR <b>Jones &amp; Laughlin Steel Corp.</b>	<b>3001 Dickey Road East Chicago, IN 46312</b>	<b>219-391-2531</b>	<b>IND005462601</b>
TRANSPORTER NO. 1 <b>Industrial Disposal Corp.</b>	<b>P.O. Box 59 East Chicago, IN 46312</b>	<b>219-397-2664</b>	<b>IND044250587</b>
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY <b>Gary Land Development =</b>	<b>P.O. Box 6056 Gary, IN 46406</b>	<b>219-944-7858</b>	<b>IND077005916</b>

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO.	TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. <b>Hazardous Waste Liquid or Solid Nos</b>	<b>12-ORM-E</b>	<b>NA9189</b>				<b>X</b>	<b>3000</b>	<b>X</b>				<b>1</b>	<b>ROL</b>	<b>T</b>	<b>K087</b>
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

**Tar Decanter Sludge**

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Tingey (ER)</i>	TITLE <i>Super Clerk</i>	DATE TO BE SHIPPED MONTH <b>5</b> DAY <b>4</b> YEAR <b>81</b>	EXPECTED ARRIVAL DATE MONTH <b>5</b> DAY <b>4</b> YEAR <b>81</b>
TRANSPORTER No. 1 HWT ID No. <b>1303N</b> <b>2692K</b>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Horman</i>	DATE RECEIVED MONTH <b>5</b> DAY <b>4</b> YEAR <b>81</b>	

**1 PART B**

TEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Horman</i>	DATE DELIVERED MONTH <b>5</b> DAY <b>4</b> YEAR <b>81</b>
Transporter No. 2 HWT ID No. <input type="checkbox"/>	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>FK</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>FK</i>	DATE RECEIVED MONTH <b>5</b> DAY <b>4</b> YEAR <b>81</b>
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	
Handling Method 1 <b>D81</b> 2 3 4	
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>DK-HA Boyl</i>	DATE RECEIVED MONTH <b>5</b> DAY <b>7</b> YEAR <b>81</b>

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;

7302 - **0207**

# Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using  
a ballpoint pen - PRESS HARD

## HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 02073

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR <b>Jones &amp; Laughlin Steel Corp.</b>	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 <b>Industrial Disposal Corp.</b>	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY <b>Gary Land Development</b>	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

TO BE FILLED OUT BY GENERATOR

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. <b>Hazardous Waste Liquid or Solid Nos</b>	<b>12-ORM-E</b>	<b>NA9189</b>				<b>X</b>	<b>3000</b>	<b>X</b>				<b>1</b>	<b>ROL</b>	<b>T</b>	<b>K087</b>
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

**Tar Decanter Sludge**

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nags</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH DAY YEAR <b>5-18-81</b>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <b>5-18-81</b>
Transporter HWT ID No. <b>1305N</b>	STATE <b>IN</b>	NUMBER <b>269812</b>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James Thomas</i>
			DATE RECEIVED MONTH DAY YEAR <b>5-18-81</b>

1 PART B

TEAR AT THIS PERFORATION

TO BE FILLED OUT BY TRANSPORTER

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James Thomas</i>	DATE DELIVERED MONTH DAY YEAR <b>5-18-81</b>
Transporter No. 2 HWT ID No. <b>1305N</b>	DATE RECEIVED MONTH DAY YEAR <b>5-18-81</b>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR <b>5-18-81</b>

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method 1 <b>D81</b> 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Steve E. Nags</i>	DATE RECEIVED MONTH DAY YEAR <b>5-18-81</b>

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 282-9378; IND. (317) 633-0683; ILL. (217) 782-3637

DOCUMENT NO. 7302 - 0207

Please TYPE or PRINT clearly, using  
a ballpoint pen - PRESS HARD

## HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 01823

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Co.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916 Gary Develop

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE	
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS				
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	ROL	T	K087
2.															
3.															
4.															

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment  
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagel</i>	TITLE <i>Supt. Clark</i>	DATE TO BE SHIPPED MONTH 5 DAY 22 YEAR 81	EXPECTED ARRIVAL DATE MONTH 5 DAY 22 YEAR 81
Transporter HWT ID No. 130711	STATE IN	NUMBER E 19214	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>James H.</i>
			DATE RECEIVED MONTH 5 DAY 22 YEAR 81

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>James H.</i>			DATE DELIVERED MONTH 5 DAY 22 YEAR 81
Transporter No. 2 HWT ID No.	STATE	NUMBER	TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT
			DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT			DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons  
For And Disposition of Rejected Materials.

Handling Method

1	D8
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>Robert B.</i>	TITLE	DATE RECEIVED MONTH DAY YEAR <i>11 PM</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706; OHIO (800) 292-0378; IND. (317) 633-0683; ILL. (217) 782-3637		

DOCUMENT NO.

7302 - 0182

TO BE FILLED OUT BY GENERATOR

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

leat TYPE or PRINT clearly, using ballpoint pen - PRESS HARD

leat TYPE or PRINT clearly, using ballpoint pen - PRESS HARD

# HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 03197

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐

Out Of A Total Of ☐

The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189					X 3000	X				1 A.C.	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nagy</i>	TITLE <i>Supt. Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR 6 26 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 6 26 81
Transporter HWT ID No. 129 EN 2647R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Kowalski</i>	DATE RECEIVED MONTH DAY YEAR 6/26/81	

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Kowalski</i>	DATE DELIVERED MONTH DAY YEAR 6/26/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR 6/26/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.

Handling Method

1	D-81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>John Kowalski</i>	TITLE	DATE RECEIVED MONTH DAY YEAR 6-26-81
---	-------	--

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE

7302 03101

PLEASE TYPE OR PRINT clearly, using  
ballpoint pen - PRESS HARD

## HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 02078

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR Jones & Laughlin Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IN DO05462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1	ROL T	K087

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment  
if a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Nagy (ER)</i>	TITLE <i>Super's Clerk</i>	DATE TO BE SHIPPED MONTH DAY YEAR <i>7-1-81</i>	EXPECTED ARRIVAL DATE MONTH DAY YEAR <i>7-1-81</i>
Transporter HWT D No. <i>142</i>	STATE <i>IN</i>	NUMBER <i>2</i>	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Jane H...</i>
			DATE RECEIVED MONTH DAY YEAR <i>7-1-81</i>

YEAR AT THIS PERFORATION  
YEAR AT THIS PERFORATION

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Jane H...</i>	DATE DELIVERED MONTH DAY YEAR <i>7-1-81</i>
Transporter No. 2 HWT ID No.	DATE RECEIVED MONTH DAY YEAR <i>7-1-81</i>
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Method: 1 <i>D2</i> 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN Boyd</i>	TITLE <i>R. J. N. 7-1-81</i>
IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-8802 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4700;	DATE RECEIVED MONTH DAY YEAR <i>7-1-81</i>

7302

- 02078

# Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using  
a ballpoint pen. PRESS HARD

## HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08324

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐ Out Of A Total Of ☐ The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189				X	3000	X				1 R.L.	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve T. [Signature]</i>	TITLE Super's Clerk	DATE TO BE SHIPPED MONTH 12 DAY 3 YEAR 81	EXPECTED ARRIVAL DATE MONTH 12 DAY 3 YEAR 81
TRANSPORTER HWT ID No. 129 EN 2697R	STATE NUMBER	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>[Signature]</i>	DATE RECEIVED MONTH 12 DAY 3 YEAR 81

YEAR AT THIS PERFORMANCE

1 PART B

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>[Signature]</i>	DATE DELIVERED MONTH 12 DAY 3 YEAR 81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT	DATE RECEIVED MONTH DAY YEAR
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT	DATE DELIVERED MONTH DAY YEAR
Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.	Handling Melt 1 7-2 2 3 4
TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>[Signature]</i>	TITLE DATE RECEIVED MONTH 12 DAY 3 YEAR 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE  
STATE: PA (717) 787-4343; MICH. (800) 292-4706;

08324

## Jones &amp; Laughlin Steel Corporation / an LTV company

## HAZARDOUS WASTE MANIFEST

Please TYPE or PRINT clearly, using  
a ballpoint pen - PRESS HARD

1 PART A

DOCUMENT NO. 7302 - 12947

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR J&L Steel Corp.	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 Industrial Disposal Corp.	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY Gary Land Development	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No. ☐Out Of A Total Of ☐The First Manifest Document No. Is ☐

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid Nos	12-ORM-E	NA9189				X	3000	X				1 ROL	T	K087
2.														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment  
of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

Tar Decanter Sludge

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve Mago</i>	TITLE <i>Superintendent</i>	DATE TO BE SHIPPED MONTH DAY YEAR 10 15 81	EXPECTED ARRIVAL DATE MONTH DAY YEAR 10 15 81
Transporter HWT ID No. 129	STATE IN	NUMBER 26972	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>John Trench</i>
			DATE RECEIVED MONTH DAY YEAR 10/15/81

TEAR AT THIS PERFORATION

1 PART B	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>John Trench</i>	DATE DELIVERED MONTH DAY YEAR 10/15/81
Transporter No. 2 HWT ID No.	STATE IN	NUMBER 26972
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT		DATE RECEIVED MONTH DAY YEAR 10/15/81
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT		DATE DELIVERED MONTH DAY YEAR 10/15/81

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons  
For And Disposition of Rejected Materials.

Handling Method

1	D-81
2	
3	
4	

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION <i>BRIAN BOYD</i>	TITLE <i>Superintendent</i>	DATE RECEIVED MONTH DAY YEAR 10-15-81
--	--------------------------------	---

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE

DA (312) 787-4343 MICH. (800) 292-4706;

7302 - 12947

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TRANSPORTER

TO BE FILLED OUT BY TSD FACILITY

# Jones & Laughlin Steel Corporation / an LTV company

Please TYPE or PRINT clearly, using a ballpoint pen - PRESS HARD

## HAZARDOUS WASTE MANIFEST

DOCUMENT NO. 7302 - 08322

1 PART A

NAME	SITE ADDRESS	PHONE NO.	EPA I.D. NO.
GENERATOR <b>J&amp;L Steel Corp.</b>	3001 Dickey Road East Chicago, IN 46312	219-391-2531	IND005462601
TRANSPORTER NO. 1 <b>Industrial Disposal Corp.</b>	P.O. Box 59 East Chicago, IN 46312	219-397-2664	IND044250587
TRANSPORTER NO. 2 (IF ANY)			
TREATMENT, STORAGE OR DISPOSAL FACILITY <b>Gary Land Development</b>	P.O. Box 6056 Gary, IN 46406	219-944-7858	IND077005916

IF MORE THAN TWO TRANSPORTERS ARE TO BE UTILIZED, FILL OUT THE FOLLOWING AS APPROPRIATE

This Form Is No.  Out Of A Total Of  The First Manifest Document No. Is

PROPER US DOT SHIPPING NAME	US DOT HAZARD CLASS	UN NUMBER	FORM				QUANTITY	UNITS				CONTAINERS NO. TYPE	EPA HAZ CODE	EPA WASTE TYPE
			SOLID	LIQUID	GAS	SLUDGE		GALLONS	CU YDS	POUNDS	TONS			
1. Hazardous Waste Liquid or Solid, N.O.S.	ORM-E-12	NA9189				X	3000	X				1 ROLL	T	K087
2. Tar Decanter Sludge														
3.														
4.														

Special Handling Instructions Including Container Exemption (i.e. Identification of Additional Wastes Included in Shipment of a Non-Hazardous Nature Which Do Not Have to be Manifested.)

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labelled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S., EPA, and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

GENERATOR'S SIGNATURE <i>Steve E. Nye</i>		TITLE <i>Supt. Clerk</i>		DATE TO BE SHIPPED MONTH DAY YEAR 11 23 81			EXPECTED ARRIVAL DATE MONTH DAY YEAR 11 23 81		
Transporter HWT ID No. 124	STATE IN	NUMBER 2692R	TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT <i>Richard Roach</i>			DATE RECEIVED MONTH DAY YEAR 11 23 81			

1 PART B

YEAR AT THIS PERFORATION

TRANSPORTER NO. 1 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT <i>Richard Roach</i>				DATE DELIVERED MONTH DAY YEAR 11 23 81			
Transporter No. 2 HWT ID No. 124				TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF RECEIPT OF SHIPMENT			
TRANSPORTER NO. 2 SIGNATURE AND CERTIFICATION OF DELIVERY AND NON-TAMPERING WITH SHIPMENT				DATE RECEIVED MONTH DAY YEAR			

Treatment, Storage or Disposal Facility Indication of Any Differences Between Manifest And Shipment or Listing of Reasons For And Disposition of Rejected Materials.

Handling Method

1 D81  
2  
3  
4

TREATMENT, STORAGE OR DISPOSAL FACILITY SIGNATURE AND CERTIFICATION

TITLE

DATE RECEIVED  
MONTH DAY YEAR  
11 25 81

IN CASE OF AN EMERGENCY OR SPILL IMMEDIATELY CALL THE NATIONAL RESPONSE CENTER (800) 424-RR02 AND THE STATE : PA. (717) 787-4343; MICH. (800) 292-4706;

- 08322